

# SAFETY CERTIFICATE

## TEMPORARY BUILDING: KV BARAMULLA

1.	Name of KV	Kendriya Vidyalaya Baramulla C/O 56 APO, 19 INF DIV., Baramulla
2.	Name/No of temporary Building	Temporary School Building Consists of Class Rooms, Laboratories, and Toilet etc. Total No of Building +07 Nos Two barracks were burnt to ashes in 2012.
3.	Whether Buildings are safe?	Yes <i>it is structurally stable</i>
4.	Major/Minor structural repair projected by Vidyalaya	NIL
5.	Major/Minor structural repair are done by sponsoring Agency during current years	Special Repair has been done in the major part of the school building.
6.	Additional requirements of Classrooms/Accommodation provided by agency	N.A
7.	Space of School is adequate	Yes <i>for current strength</i>
8.	Whether Water/Electric supply and Sanitary Facilities are provided by Sponsoring Agency?	Yes
9.	Whether the school building is safe from fire and electricity point of view?	Yes, but it does not have enough fire exits. <i>One staircase for first floor of OS bldg. 1 main gate and 3 wicket gates for fire exit of entire school campus.</i>

File No:- 4000/ES/ICI/EM



Garrison Engineer  
(Bhavesh Mudgal)  
Lt Col  
Garrison Engineer

COUNTERSIGNED

CHAIRMAN  
VMC, KV BARAMULLA

अध्यक्ष / CHAIRMAN  
वि. प्र. स. / VMC  
क. वि. बारामुल्ला / K. V. BARAMULLA